

## RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080127-3

No. 11117

RECEIVED FROM

Carl . . Holmes Co.

DATE REC'D 1-31-57

P.O. NO. 236

VENDOR PACKING SLIP NO. 9062

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS
									ACCEPTED	REJECTED	
10	322	000000	22064	1	0	00	00	02			
DRAWING NO. AND DESCRIPTION											
730145-00003 Model, #82031L (Union Switch) & Signal Post. 105											

RECEIVED  
BYINSPECTED  
BY

DATE

RECEIPTS RETURNED  
ON SHIP MEMO NO.

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST. PASADENA, CALIF.

No. 11119

RECEIVED FROM

DATE REC'D 1-31-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS
									ACCEPTED	REJECTED	
	322	000000	22039	0	0	00	00				
DRAWING NO. AND DESCRIPTION											
730145-00003 Model, #82031L (Union Switch) & Signal Post. 105											

RECEIVED

BY

DATE

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080127-3

RECEIPTS RETURNED

ON SHIP MEMO NO.